

Message

Sent: 11/29/2019 12:17:08 PM
To: Carroll, Craig [Carroll.Craig@epa.gov]; Adam Adams (Adams.Adam@epa.gov) [Adams.Adam@epa.gov]; Rouse, Philip [rouse.philip@epa.gov]; Delgado, Eric (Delgado.Eric@epa.gov) [Delgado.Eric@epa.gov]
Subject: Update for Mgmt Update

Currently there are nine fires burning, 3 of which are being actively fed. The facility has been working a block isolation plan to address the fires which has been successful in slowing down some of the fires. To prevent releases or fuel or vapors, the facility is not extinguishing fires where gas is actively leaking.

In the section talking about the sheen the following change and then add a bullet –

On 11/28/2019, a sheen was observed in the discharge canal. TPC brought in an OSRO who have deployed 4 drum skimmers, boom, sorbents, and trash pumps to remediate to the sheen. Additional personnel and equipment are scheduled to arrive on November 29, 2019 to contain the sheen.

New Bullett

The site hired Clean Harbors to address waste and product recovery.



Matthew Loesel
U.S. EPA - FOSC
1201 Elm Street
Suite 500 (65ED-EC)
Dallas, Texas 75270
(214) 738 0674 (mobile)
(214) 665 8544 (office)
loesel.matthew@epa.gov